



Calibration Procedure

PXIe-5413

July 2024

376945D-01

CALIBRATION PROCEDURE

PXIe-5413

PXIe, 20 MHz Bandwidth, 16-Bit PXI Waveform Generator

This document contains the verification and adjustment procedures for the PXIe-5413. Refer to ni.com/calibration for more information about calibration solutions.

Contents

Required Software	1
Related Documentation.....	2
Test Equipment	2
Test Conditions	4
Password.....	5
Calibration Interval.....	5
As-Found and As-Left Limits.....	5
Calibration Overview.....	5
Verifying the PXIe-5413	6
Verifying Timebase Accuracy.....	6
Verifying DC Voltage Accuracy.....	7
Verifying AC Amplitude Accuracy.....	9
Verifying Passband Flatness Accuracy.....	11
Adjusting the PXIe-5413	14
Adjusting Timebase	14
Adjusting DC Voltage	15
Adjusting Passband Flatness.....	16
Reverification.....	18
Setting the Calibration Date and Due Date	18
NI Services	18

Required Software



Note Ensure that the most recent version of the required driver software is installed before conducting the calibration. C API is also supported.

Calibrating the PXIe-5413 requires you to install the following software on the calibration system:

- NI-FGEN 17.1 or later
The PXIe-5413 was first supported in NI-FGEN 17.1.
- LabVIEW 2016 or later, Full Development System or Professional Development System

You can download all required software from ni.com/downloads.



Related Documentation

For additional information, refer to the following documents as you perform the calibration procedure:

- *PXIe-5413 Getting Started Guide*
- *PXIe-5413 Specifications*
- *NI Signal Generators Help*
- *LabVIEW Help*

Visit ni.com/docs for the latest versions of these documents.

Test Equipment

Refer to the following table for a list of necessary test equipment, minimum requirements for the test equipment, and model recommendations for calibration of the PXIe-5413.

If you do not have the recommended equipment, select a substitute calibration standard using the minimum requirements specifications listed in the table.

Table 1. PXIe-5413 Test Equipment

Equipment	Recommended Model	Where Used	Minimum Requirements
Oscilloscope	PXIe-5160 or PXIe-5171	Verifications: • Timebase accuracy Adjustments: • Timebase	Frequency resolution: 0.1 Hz The ability to measure sine waves ≥ 10 MHz with amplitudes of 2 V _{pk-pk} to 5 V _{pk-pk} with 50 Ω input impedance.
SMA (m)-to-SMA (m) cable	—	Verifications: • Timebase accuracy Adjustments: • Timebase	Frequency range: DC to 100 MHz Impedance: 50 Ω Length: <1 m

Table 1. PXIe-5413 Test Equipment (Continued)

Equipment	Recommended Model	Where Used	Minimum Requirements
Precision frequency reference	PXIe-6674T or Rubidium reference	Verifications: - Timebase accuracy Adjustments: - Timebase	Frequency accuracy: 100 ppb The ability to PLL lock to the oscilloscope.
DMM	PXI-4071	Verifications: - DC voltage accuracy - AC amplitude accuracy Adjustments: - DC voltage	DC voltage range: ± 5 V DC voltage accuracy: < 40 ppm AC voltage accuracy: $\pm 0.1\%$ of reading at 50 kHz AC Input Range: 0.05 V _{RMS} to 5 V _{RMS} AC Input Impedance: ≥ 10 M Ω Bandwidth: ≥ 100 kHz
Double banana plug-to-BNC (f)	Pasternak PE9008	Verifications: - DC voltage accuracy - AC amplitude accuracy Adjustments: - DC voltage	Impedance: 50 Ω
SMA (m)-to-BNC (m) cable	—	Verifications: - DC voltage accuracy - AC amplitude accuracy Adjustments: - DC voltage	Frequency range: DC to 1 MHz Impedance: 50 Ω Length: < 1 m

Table 1. PXIe-5413 Test Equipment (Continued)

Equipment	Recommended Model	Where Used	Minimum Requirements
Power sensor	Rohde & Schwarz (R&S) NRP-Z91	Verifications: - Passband flatness accuracy Adjustments: - Passband flatness	Range: -30 dBm to 23 dBm Frequency range: 50 kHz to 100 MHz Absolute Power Accuracy: <0.048 dB for <100 MHz Relative Power Accuracy: <0.022 dB for <100 MHz VSWR: <1.11
SMA (m)-to-N (f) adapter	—	Verifications: - Passband flatness accuracy Adjustments: - Passband flatness	Frequency range: DC to 100 MHz Impedance: 50 Ω

Test Conditions

The following setup and environmental conditions are required to ensure the PXIe-5413 meets published specifications:

- The PXIe-5413 is warmed up for 15 minutes at ambient temperature. Warm up begins after the chassis is powered and the PXIe-5413 is recognized by the host and configured using NI-FGEN.
- All test instruments are warmed up for at least the period of time stated in the documentation for each instrument and self-calibration is performed. The warm-up time ensures that the test instruments are at a stable operating temperature.
- Keep cabling as short as possible. Long cables act as antennas, picking up extra noise that can affect measurements.
- Verify that all connections to the PXIe-5413, including front panel connections and screws, are secure.
- Use shielded copper wire for all cable connections to the device. Use twisted-pair wire to eliminate noise and thermal offsets.
- Maintain an ambient temperature of $23\text{ }^{\circ}\text{C} \pm 3\text{ }^{\circ}\text{C}$.
- Keep relative humidity between 10% and 90%, noncondensing.

- Ensure that the PXI chassis fan speed is set to HIGH, that the fan filters (if present) are clean, and that the empty slots contain slot blockers and filler panels. For more information about cooling, refer to the *Maintain Forced-Air Cooling Note to Users* document available at ni.com/docs.
- Plug the PXI chassis and any other instrument standards into the same power strip to avoid ground loops.

Password

The default password for password-protected operations is NI.

Related Information

[Adjusting the PXIe-5413](#) on page 14

[Setting the Calibration Date and Due Date](#) on page 18

Calibration Interval

Recommended calibration interval	2 years
----------------------------------	---------

As-Found and As-Left Limits

The as-found limits are the published specifications for the PXIe-5413. NI uses these limits to determine whether the PXIe-5413 meets the specifications when it is received for calibration. Use the as-found limits during initial verification.

The as-left calibration limits are equal to the published NI specifications for the PXIe-5413, less guard bands for measurement uncertainty, temperature drift, and drift over time. NI uses these limits to reduce the probability that the instrument will be outside the published specification limits at the end of the calibration cycle. Use the as-left limits when performing verification after adjustment.

Calibration Overview

Install the PXIe-5413 and configure it in NI Measurement & Automation Explorer (MAX) before calibrating.

Calibration includes the following steps:

1. Self-calibration—Let the PXIe-5413 warm up for 15 minutes before self-calibrating the PXIe-5413 by clicking the **Self-Calibrate** button in MAX or calling niFgen Self Cal.
2. Verification—Verify the existing operation of the device. This step confirms whether the device is operating within the published specification prior to adjustment.
3. Adjustment—Perform an external adjustment of the calibration constants of the device. The adjustment procedure automatically stores the calibration date and temperature on the EEPROM to allow traceability.

4. Self-calibration—Let the PXIe-5413 warm up for 15 minutes before self-calibrating the PXIe-5413 by clicking the **Self-Calibrate** button in MAX or calling niFgen Self Cal.
5. Reverification—Repeat the Verification procedure to ensure that the device is operating within the published specifications after adjustment.

Refer to the following sections to complete each procedure.

Related Information

[Verifying the PXIe-5413](#) on page 6

[Adjusting the PXIe-5413](#) on page 14

Verifying the PXIe-5413

The performance verification procedures assume that adequate traceable uncertainties are available for the calibration references.

Self-calibrate the PXIe-5413 and all test instruments before beginning the verification procedures.



Note Verification of the PXIe-5413 is complete only after you have successfully completed all verification tests in this section using the as-found limits.

Related Information

[Calibration Overview](#) on page 5

Verifying Timebase Accuracy

Follow this procedure to verify the frequency accuracy of the PXIe-5413 onboard timebase (TCXO) using an oscilloscope.

Refer to the following table as you complete the following steps.

Table 3. Timebase Accuracy Verification

As-Found Limit	As-Left Limit
$\pm(1.5 \text{ ppm} + 1 \text{ ppm per year}^1)$	$\pm 0.28 \text{ ppm}$

1. Connect one end of the SMA (m)-to-SMA (m) cable to a channel of the PXIe-5413 and the other end to a channel of the oscilloscope.



Note Timebase accuracy verification can be performed on either channel of the two-channel PXIe-5413.

2. Lock the oscilloscope to the precision frequency reference using the PXI Clock.

¹ Where time drift starts at the latest external calibration date.

3. Configure the oscilloscope to acquire a 10 MHz sine wave with the following settings:
 - **Vertical range:** 5 V_{pk-pk}
 - **Sample rate:** 250 MS/s
 - **Input impedance:** 50 Ω
 - **Minimum number of points:** 1,048,576 samples
4. Configure the PXIe-5413 with the following settings:
 - **Channel:** Channel of the PXIe-5413 connected to the oscilloscope
 - **Output impedance:** 50 Ω
 - **Output mode:** Standard Function
 - **Waveform type:** Sine
 - **Frequency:** 10 MHz
 - **Amplitude:** 2.5 V_{pk-pk}
 - **Offset:** 0 V
 - **Reference Clock source:** Onboard Reference Clock
5. Wait 1 second for settling.
6. Measure the peak frequency (Hz) using the oscilloscope and the Extract Single Tone Information VI and record this as F_{Measured} .
7. Calculate the timebase error using the following formula:

$$\text{Timebase Error (ppm)} = \left(\frac{\text{Measured} - 10^7}{10} \right)$$

8. Compare the frequency error to the appropriate limit from the [Timebase Accuracy Verification](#) table.



Note Timebase accuracy verification is only required on one channel of the two-channel PXIe-5413.

Verifying DC Voltage Accuracy

Follow this procedure to verify the DC voltage accuracy of the PXIe-5413 by comparing the voltage sourced by the PXIe-5413 to the value measured by the DMM.

Refer to the following table as you complete the following steps.

Table 4. DC Voltage Accuracy Verification

	DMM Range (V)	Amplitude Range (V_{pk-pk})	Offset (V)	Expected Amplitude (V)	As-Found Test Limit (mV)	As-Left Test Limit (mV)
1	10	7.340	3.670	3.670	±39.04	±11.17
2		2.268	1.134	1.134	±12.41	±3.45
3		2.185	1.092	1.092	±11.97	±3.33
4		2.102	1.051	1.051	±11.54	±3.20
5		2.019	1.009	1.009	±11.10	±3.07
6	1	1.936	0.968	0.968	±10.66	±2.95
7		1.854	0.927	0.927	±10.23	±2.82
8		1.770	0.885	0.885	±9.79	±2.69
9		1.686	0.843	0.843	±9.35	±2.57
10		0.696	0.348	0.348	±4.15	±1.06
11		0.214	0.107	0.107	±1.62	±0.68
12	0.1	0.066	0.033	0.033	±0.85	±0.53
13	10	7.340	-3.670	-3.670	±39.04	±11.17
14		2.268	-1.134	-1.134	±12.41	±3.45
15		2.185	-1.092	-1.092	±11.97	±3.33
16		2.102	-1.051	-1.051	±11.54	±3.20
17		2.019	-1.009	-1.009	±11.10	±3.07
18	1	1.936	-0.968	-0.968	±10.66	±2.95
19		1.854	-0.927	-0.927	±10.23	±2.82
20		1.770	-0.885	-0.885	±9.79	±2.69
21		1.686	-0.843	-0.843	±9.35	±2.57
22		0.696	-0.348	-0.348	±4.15	±1.06
23		0.214	-0.107	-0.107	±1.62	±0.68
24	0.1	0.066	-0.033	-0.033	±0.85	±0.53

1. Connect one end of the SMA (m)-to-BNC (m) cable to CH 0 of the PXIe-5413. Connect the other end to the double banana plug-to-BNC (f) adapter, and connect the double banana plug-to-BNC (f) adapter to the HI and LO connectors of the DMM.
2. Configure the DMM with the following settings:
 - **Function:** DC Voltage
 - **Resolution:** 7.5 digits
 - **Aperture time:** 100 ms
 - **Number of averages:** 4
 - **Auto zero:** Enabled
 - **ADC calibration:** Enabled
 - **Vertical range:** *DMM range* listed in the [DC Voltage Accuracy Verification](#) table
3. Configure the PXIe-5413 with the following settings:
 - **Channel:** Channel of the PXIe-5413 connected to the DMM
 - **Load impedance:** 1 MΩ
 - **Output mode:** Standard Function
 - **Waveform type:** User
 - **Amplitude:** *Amplitude range* listed in the [DC Voltage Accuracy Verification](#) table
 - **Offset:** *Offset* listed in the [DC Voltage Accuracy Verification](#) table
 - **Waveform data:** Array of zeros
 - **Waveform size:** 8,192 samples
4. Wait 1 second for settling.
5. Measure the DC voltage (V) using the DMM and record this as *DC Voltage Measured*.
6. Calculate the DC voltage error using the following formula:

$$DC\ Voltage\ Error\ (mV) = (DC\ Voltage\ Measured - Expected\ Amplitude) * 10^3$$

where *Expected Amplitude* is the expected amplitude (V) listed in the [DC Voltage Accuracy Verification](#) table.
7. Compare the DC voltage error to the appropriate limit from the [DC Voltage Accuracy Verification](#) table.
8. Repeat steps 2 through 7 for each configuration listed in the [DC Voltage Accuracy Verification](#) table.
9. If you are verifying a two-channel PXIe-5413, complete the following steps to verify CH 1:
 - a) Abort waveform generation on the PXIe-5413.
 - b) Disconnect the SMA (m)-to-BNC (m) cable from CH 0 and connect it to CH 1 of the PXIe-5413.
 - c) Repeat steps 2 through 8.

Verifying AC Amplitude Accuracy

Follow this procedure to verify the AC amplitude accuracy of the PXIe-5413 by comparing the amplitude sourced by the PXIe-5413 to the amplitude measured by the DMM.

Refer to the following table as you complete the following steps.

Table 5. AC Amplitude Accuracy Verification

	DMM Range (V_{RMS})	Amplitude Range (V_{pk-pk})	Expected Amplitude (V_{pk-pk})	As-Found Test Limit (mV)	As-Left Test Limit (mV)
1	5	7.34	7.34	±74.40	±32.66
2		2.27	2.27	±23.70	±10.10
3		2.18	2.18	±22.80	±9.70
4		2.1	2.1	±22.00	±9.35
5		2.02	2.02	±21.20	±8.99
6		1.94	1.94	±20.40	±8.63
7		1.85	1.85	±19.50	±8.23
8		1.77	1.77	±18.70	±7.88
9		1.68	1.68	±17.80	±7.48
10	0.5	0.69	0.69	±7.90	±3.07
11		0.21	0.21	±3.10	±1.50
12	0.05	0.065	0.065	±1.65	±0.81

1. Connect one end of the SMA (m)-to-BNC (m) cable to CH 0 of the PXIe-5413. Connect the other end to the double banana plug-to-BNC (f) adapter, and connect the double banana plug-to-BNC (f) adapter to the HI and LO connectors of the DMM.
2. Configure the DMM with the following settings:
 - **Function:** AC Voltage
 - **Resolution:** 6.5 digits
 - **Aperture time:** 100 ms
 - **Number of averages:** 4
 - **Minimum frequency:** 49 kHz
 - **Auto zero:** Enabled
 - **ADC calibration:** Enabled
 - **Vertical range:** *DMM range* listed in the [AC Amplitude Accuracy Verification](#) table
3. Configure the PXIe-5413 with the following settings:
 - **Channel:** Channel of the PXIe-5413 connected to the DMM
 - **Load impedance:** 1 MΩ
 - **Output mode:** Standard Function
 - **Waveform type:** Sine
 - **Frequency:** 50 kHz

- **Amplitude:** *Amplitude range* listed in the [AC Amplitude Accuracy Verification](#) table
- **Offset:** 0 V

- Wait 1 second for settling.
- Measure the AC amplitude (V_{RMS}) using the DMM and record this as $AC\ Amplitude_{Measured}$.
- Convert the recorded $AC\ Amplitude_{Measured}$ voltage from V_{RMS} to V_{pk-pk} using the following formula:

$$pk - pk = RMS * 2 * \sqrt{2}$$

- Calculate the AC amplitude error using the following formula:

$$AC\ Amplitude\ Error\ (mV) = (AC\ Amplitude_{Measured} - Expected\ Amplitude) * 10^3$$

where *Expected Amplitude* is the expected amplitude (V_{pk-pk}) listed in the [AC Amplitude Accuracy Verification](#) table.

- Compare the AC amplitude error to the appropriate limit from the [AC Amplitude Accuracy Verification](#) table.
- Repeat steps 2 through 8 for each configuration listed in the [AC Amplitude Accuracy Verification](#) table.
- If you are verifying a two-channel PXIe-5413, complete the following steps to verify CH 1:
 - Abort waveform generation on the PXIe-5413.
 - Disconnect the SMA (m)-to-BNC (m) cable from CH 0 and connect it to CH 1 of the PXIe-5413.
 - Repeat steps 2 through 9.

Verifying Passband Flatness Accuracy

Follow this procedure to verify the passband flatness accuracy of the PXIe-5413 by comparing the flatness sourced by the PXIe-5413 to the value measured by the power sensor.

Refer to the following table as you complete the following steps.

Table 6. Passband Flatness Accuracy Verification

	Amplitude Range (V_{pk-pk})	Frequency (MHz)	As-Found Test Limit (dB)	As-Left Test Limit (dB)
1	3.500	0.05	—	—
2		1	±0.40	±0.25
3		20	±0.60	±0.14

Table 6. Passband Flatness Accuracy Verification (Continued)

	Amplitude Range (V _{pk-pk})	Frequency (MHz)	As-Found Test Limit (dB)	As-Left Test Limit (dB)
5	1.040	0.05	—	—
6		1	±0.40	±0.25
7		20	±0.40	±0.11
11	0.956	0.05	—	—
12		1	±0.40	±0.25
13		20	±0.40	±0.11
17	0.867	0.05	—	—
18		1	±0.40	±0.25
19		20	±0.40	±0.11
23	0.780	0.05	—	—
24		1	±0.40	±0.25
25		20	±0.40	±0.11
29	0.321	0.05	—	—
30		1	±0.40	±0.25
31		20	±0.40	±0.11
35	0.099	0.05	—	—
36		1	±0.40	±0.25
37		20	±0.40	±0.11

1. Connect the SMA (m)-to-N (f) adapter to the power sensor.
2. Zero the power sensor.
 - a) Ensure that the power sensor is not connected to any signals.
 - b) Zero the power sensor using the built-in function, according to the power sensor documentation.
3. Connect the power sensor with the SMA (m)-to-N (f) adapter attached to CH 0 of the PXIe-5413.



Note Ensure the power sensor is supported to the extent that excessive strain is not applied to the connected channel of the PXIe-5413 or to the power sensor connector.

4. Configure the power sensor with the following settings:
 - **Maximum noise ratio:** 0.005 dB
 - **Auto range:** Enabled
 - **Power measurement:** Continuous average
 - **Path selection:** Automatic
 - **Averaging:** Automatic
 - **Aperture:** 20 ms
 - **Timeout:** 10 s
 - **Frequency:** *Frequency* listed in the [Passband Flatness Accuracy Verification](#) table
5. Configure the PXIe-5413 with the following settings:
 - **Load impedance:** 50 Ω
 - **Output mode:** Standard Function
 - **Waveform type:** Sine
 - **Amplitude:** *Amplitude range* listed in the [Passband Flatness Accuracy Verification](#) table
 - **Frequency:** *Frequency* listed in the [Passband Flatness Accuracy Verification](#) table
 - **Offset:** 0 V
6. Wait 1 second for settling.
7. Measure and record the power (dBm) using the power sensor.
 - When the power is measured at 0.05 MHz, record this as $P_{\text{Measured at 0.05 MHz}}$.
 - When the power is measured at all frequencies other than 0.05 MHz, record this as $P_{\text{Measured at Current Test Frequency}}$.
8. Skip this step if the PXIe-5413 frequency is configured to 0.05 MHz. Calculate the passband flatness error using the following formula:

$$\text{Passband Flatness Error (dB)} = P_{\text{Measured at 0.05 MHz}} - P_{\text{Measured at Current Test Frequency}}$$

where $P_{\text{Measured at 0.05 MHz}}$ (dBm) and $P_{\text{Measured at Current Test Frequency}}$ (dBm) are values for power measured at the same amplitude range listed in the [Passband Flatness Accuracy Verification](#) table.
9. Repeat steps 4 through 8 for each configuration listed in the [Passband Flatness Accuracy Verification](#) table.
10. For each configuration, compare the passband flatness error to the appropriate limit from the [Passband Flatness Accuracy Verification](#) table.
11. If you are verifying a two-channel PXIe-5413, complete the following steps to verify CH 1:
 - a) Abort waveform generation on the PXIe-5413.
 - b) Disconnect the SMA (m)-to-N (f) adapter and power sensor assembly from CH 0 and connect the assembly to CH 1 of the PXIe-5413.
 - c) Repeat steps 4 through 10.

Adjusting the PXIe-5413

Follow this procedure to adjust the PXIe-5413 to meet published specifications.



Note All adjustments must be completed in the same external calibration session.

1. Call niFgen ni5433 Open Ext Cal Session to obtain an external calibration session.
2. Complete the [Adjusting Timebase](#) procedure.
3. Complete the [Adjusting DC Voltage](#) procedure.
4. Complete the [Adjusting Passband Flatness](#) procedure.
5. Call niFgen ni5433 Close Ext Cal Session with the following settings:
 - **Action:** If the external adjustment procedure completed without any errors, set this control to Commit to store the new calibration constants, adjustment time, adjustment date, and adjustment temperature to the onboard memory. If any errors occurred during the external adjustment procedure, or if you want to abort the operation, set the control to Abort to discard the new calibration constants without changing any of the calibration data stored in the onboard memory.

Self-calibrate the PXIe-5413 after completing adjustment and before reverification.

Related Information

[Password](#) on page 5

[Calibration Overview](#) on page 5

Adjusting Timebase

Follow this procedure to adjust the internal timebase reference (TCXO) of the PXIe-5413.

1. Connect one end of the SMA (m)-to-SMA (m) cable to a channel of the PXIe-5413 and the other end to a channel of the oscilloscope.



Note Timebase adjustment can be performed on either channel of the two-channel PXIe-5413.

2. Lock the oscilloscope to the precision frequency reference using the PXI Clock.
3. Configure the oscilloscope with the following settings:
 - **Vertical range:** 5 V_{pk-pk}
 - **Sample rate:** 250 MS/s
 - **Input impedance:** 50 Ω
 - **Minimum number of points:** 1,048,576 samples
4. Call niFgen ni5433_Timebase_Cal_Initialize (niFgen ni5433 Timebase Cal Initialize VI) with the following settings:
 - **Channel:** Channel of the PXIe-5413 connected to the oscilloscope
5. Call niFgen_ni5433_Timebase_Cal_Configure (niFgen ni5433 Timebase Cal Configure VI).
6. Wait 1 second for settling.
7. Measure the frequency of the signal using the oscilloscope and the Extract Single Tone Information VI.

8. Call `niFgen_ni5433_Timebase_Cal_Adjust` (niFgen ni5433 Timebase Cal Adjust VI) with the following settings:
 - **Measured Frequency:** Frequency of the waveform present on the connected channel of the PXIe-5413 and measured by the oscilloscope in the previous step
9. If the **Timebase_Cal_Complete** (Timebase Cal Complete) output of `niFgen_ni5433_Timebase_Cal_Adjust` (niFgen ni5433 Timebase Cal Adjust VI) returns **VI_FALSE** (False), repeat steps 5 through 8 until **Timebase_Cal_Complete** (Timebase Cal Complete) returns **VI_TRUE** (True).



Note Timebase adjustment is only required on one channel of the two-channel PXIe-5413.

Adjusting DC Voltage

Follow this procedure to adjust the DC voltage of the PXIe-5413.

1. Connect one end of the SMA (m)-to-BNC (m) cable to a channel of the PXIe-5413. Connect the other end to the double banana plug-to-BNC (f) adapter, and connect the double banana plug-to-BNC (f) adapter to the HI and LO connectors of the DMM.
-
- Note** DC voltage adjustment can be performed on either channel of the two-channel PXIe-5413.
2. Call `niFgen_ni5433_ADC_Cal_Initialize` (niFgen ni5433 ADC Cal Initialize VI) with the following settings:
 - **Channel:** Channel of the PXIe-5413 connected to the DMM
 3. Call `niFgen_ni5433_ADC_Cal_Configure` (niFgen ni5433 ADC Cal Configure VI) to obtain the **Approximate Voltage Generated** (V_{pk-pk}) output.
 4. Wait 1 second for settling.
 5. Configure the DMM with the following settings:
 - **Function:** DC Voltage
 - **Resolution:** 7.5 digits
 - **Aperture time:** 100 ms
 - **Number of averages:** 4
 - **Auto zero:** Enabled
 - **ADC calibration:** Enabled
 - **Range:** Range returned by the **Approximate Voltage Generated** (V_{pk-pk}) output of `niFgen_ni5433_ADC_Cal_Configure` (niFgen ni5433 ADC Cal Configure VI) in step 3
 6. Measure the voltage of the signal using the DMM.
 7. Call `niFgen_ni5433_ADC_Cal_Adjust` (niFgen ni5433 ADC Cal Adjust VI) with the following settings:
 - **Measured Voltage:** Voltage of the waveform present on the connected channel of the PXIe-5413 and measured by the DMM in the previous step
 8. If the **ADC_Cal_Complete** (ADC Cal Complete) output of `niFgen_ni5433_ADC_Cal_Adjust` (niFgen ni5433 ADC Cal Adjust VI) returns **VI_FALSE** (False), repeat steps 3 through 7 until **ADC_Cal_Complete** (ADC Cal Complete) returns **VI_TRUE** (True).



Note DC voltage adjustment is only required on one channel of the two-channel PXIe-5413.

Adjusting Passband Flatness

Complete one of the following procedures depending on the channel count of the PXIe-5413 you are adjusting:

- [Adjusting Passband Flatness of a One-Channel PXIe-5413](#)
- [Adjusting Passband Flatness of a Two-Channel PXIe-5413](#)

Adjusting Passband Flatness of a One-Channel PXIe-5413

Follow this procedure to adjust the passband flatness of a one-channel PXIe-5413.



Note Ensure the power sensor, with the SMA (m)-to-N (f) adapter attached, has been zeroed within the past hour.

1. Call `niFgen_ni5433_Flatness_Cal_Initialize` (niFgen ni5433 Flatness Cal Initialize VI).
2. Call `niFgen_ni5433_Flatness_Cal_Configure` (niFgen ni5433 Flatness Cal Configure VI).
3. Call `niFgen_ni5433_Flatness_Cal_Adjust` (niFgen ni5433 Flatness Cal Adjust VI) with the following settings:
 - **Measured Power (dBm):** 0 dBm
4. Connect the power sensor with the SMA (m)-to-N (f) adapter attached to CH 0 of the PXIe-5413.
5. Call `niFgen_ni5433_Flatness_Cal_Configure` (niFgen ni5433 Flatness Cal Configure VI) to obtain the **Current Configuration** output.
6. Configure the power sensor with the following settings:
 - **Auto range:** Enabled
 - **Maximum noise ratio:** 0.005 dB
 - **Power measurement:** Continuous average
 - **Path selection:** Automatic
 - **Averaging:** Automatic
 - **Aperture:** 20 ms
 - **Timeout:** 10 s
 - **Frequency:** Frequency returned by the **Current Configuration** (Current Configuration) output of `niFgen_ni5433_Flatness_Cal_Configure` (niFgen ni5433 Flatness Cal Configure VI) in the previous step.
7. Wait 1 second for settling.
8. Measure the power of the signal using the power sensor.
9. Call `niFgen_ni5433_Flatness_Cal_Adjust` (niFgen ni5433 Flatness Cal Adjust VI) with the following settings:
 - **Measured Power (dBm):** Power of the waveform present on CH 0 of the PXIe-5413 and measured by the power sensor in the previous step in dBm
10. If the **Flatness_Cal_Complete** (Flatness Cal Complete) output of `niFgen_ni5433_Flatness_Cal_Adjust` (niFgen ni5433 Flatness Cal Adjust VI) returns **VI_FALSE** (False), repeat steps 5 through 9 until **Flatness_Cal_Complete** (Flatness Cal Complete) returns **VI_TRUE** (True).

Adjusting Passband Flatness of a Two-Channel PXIe-5413

Follow this procedure to adjust the passband flatness of a two-channel PXIe-5413.



Note Ensure the power sensor, with the SMA (m)-to-N (f) adapter attached, has been zeroed within the past hour.

1. Call `niFgen_ni5433_Flatness_Cal_Initialize` (niFgen ni5433 Flatness Cal Initialize VI).
2. Call `niFgen_ni5433_Flatness_Cal_Configure` (niFgen ni5433 Flatness Cal Configure VI).
3. Call `niFgen_ni5433_Flatness_Cal_Adjust` (niFgen ni5433 Flatness Cal Adjust VI) with the following settings:
 - **Measured Power (dBm):** 0 dBm
4. Connect the power sensor with the SMA (m)-to-N (f) adapter attached to CH 0 of the PXIe-5413.
5. Call `niFgen_ni5433_Flatness_Cal_Configure` (niFgen ni5433 Flatness Cal Configure VI) to obtain the **Current_Configuration** (Current Configuration) and **Next_Configuration** (Next Configuration) outputs.
6. Configure the power sensor with the following settings:
 - **Auto range:** Enabled
 - **Maximum noise ratio:** 0.005 dB
 - **Power measurement:** Continuous average
 - **Path selection:** Automatic
 - **Averaging:** Automatic
 - **Aperture:** 20 ms
 - **Timeout:** 10 s
 - **Frequency:** Frequency returned by the **Current_Configuration** (Current Configuration) output of `niFgen_ni5433_Flatness_Cal_Configure` (niFgen ni5433 Flatness Cal Configure VI) in the previous step.
7. Wait 1 second for settling.
8. Measure the power of the signal using the power sensor.
9. Call `niFgen_ni5433_Flatness_Cal_Adjust` (niFgen ni5433 Flatness Cal Adjust VI) with the following settings:
 - **Measured Power (dBm):** Power of the waveform present on CH 0 of the PXIe-5413 and measured by the power sensor in the previous step in dBm
10. If the **Next_Configuration** (Next Configuration) output of `niFgen_ni5433_Flatness_Cal_Configure` (niFgen ni5433 Flatness Cal Configure VI) obtained in step 5 returns CH 0, repeat steps 5 through 9. If the **Next_Configuration** (Next Configuration) output of `niFgen_ni5433_Flatness_Cal_Configure` (niFgen ni5433 Flatness Cal Configure VI) obtained in step 5 returns CH 1, continue to step 11.
11. Connect the SMA (m)-to-N (f) adapter and power sensor assembly to CH 1 of the PXIe-5413.
12. Call `niFgen_ni5433_Flatness_Cal_Configure` (niFgen ni5433 Flatness Cal Configure VI) to obtain the **Current_Configuration** (Current Configuration) output.
13. Configure the power sensor with the following settings:
 - **Auto range:** Enabled

- **Maximum noise ratio:** 0.005 dB
- **Power measurement:** Continuous average
- **Path selection:** Automatic
- **Averaging:** Automatic
- **Aperture:** 20 ms
- **Timeout:** 10 s
- **Frequency:** Frequency returned by the **Current_Configuration** (Current Configuration) output of niFgen_ni5433_Flatness_Cal_Configure (niFgen ni5433 Flatness Cal Configure VI) in the previous step

14. Wait 1 second for settling.

15. Measure the power of the signal using the power sensor.

16. Call niFgen_ni5433_Flatness_Cal_Adjust (niFgen ni5433 Flatness Cal Adjust VI) with the following settings:

- **Measured Power (dBm):** Power of the waveform present on CH 1 of the PXIe-5413 and measured by the power sensor in the previous step in dBm

17. If the **Flatness_Cal_Complete** (Flatness Cal Complete) output of niFgen_ni5433_Flatness_Cal_Adjust (niFgen ni5433 Flatness Cal Adjust VI) returns **VI_FALSE** (False), repeat steps 12 through 16 until **Flatness_Cal_Complete** (Flatness Cal Complete) returns **VI_TRUE** (True).

Reverification

Repeat the [Verification](#) section to determine the as-left status of the PXIe-5413.



Note If any test fails reverification after performing an adjustment, verify that you have met the test conditions before returning your PXIe-5413 to NI. Refer to the [NI Services](#) section for information about support resources or service requests.

Setting the Calibration Date and Due Date

After completing all verifications or reverifications, set the calibration date and a calibration due date for the PXIe-5413 using either Measurement Automation Explorer (MAX) or the LabVIEW NI System Configuration API.

NI recommends a calibration due date of the date of external calibration plus the external calibration interval for the PXIe-5413.

- **MAX**—Navigate to the External Calibration section of the Settings tab and update the **Calibration Date** and **Calibration Due Date** entries. Click Save.
- **LabVIEW NI System Configuration API**—Use the Update Calibration VI to set the **calibration date** and **calibration due date**.

The calibration due date can be either a specific date or an interval in months.

Related Information

[Password](#) on page 5

NI Services

Visit ni.com/support to find support resources including documentation, downloads, and troubleshooting and application development self-help such as tutorials and examples.

Visit ni.com/services to learn about NI service offerings such as calibration options, repair, and replacement.

Visit ni.com/register to register your NI product. Product registration facilitates technical support and ensures that you receive important information updates from NI.

NI corporate headquarters is located at 11500 N Mopac Expwy, Austin, TX 78759-3504, US

Information is subject to change without notice. Refer to the *NI Trademarks and Logo Guidelines* at ni.com/trademarks for information on NI trademarks. Other product and company names mentioned herein are trademarks or trade names of their respective companies. For patents covering NI products/technology, refer to the appropriate location: **Help»Patents** in your software, the `patents.txt` file on your media, or the *National Instruments Patent Notice* at ni.com/patents. You can find information about end-user license agreements (EULAs) and third-party legal notices in the readme file for your NI product. Refer to the *Export Compliance Information* at ni.com/legal/export-compliance for the NI global trade compliance policy and how to obtain relevant HTS codes, ECCNs, and other import/export data. NI MAKES NO EXPRESS OR IMPLIED WARRANTIES AS TO THE ACCURACY OF THE INFORMATION CONTAINED HEREIN AND SHALL NOT BE LIABLE FOR ANY ERRORS. U.S. Government Customers: The data contained in this manual was developed at private expense and is subject to the applicable limited rights and restricted data rights as set forth in FAR 52.227-14, DFAR 252.227-7014, and DFAR 252.227-7015.

© 2017-2024 National Instruments Corporation. All rights reserved.

376945D-01 10-07-2024